


Damaged Lining

Figure 1



Prepared Surface

Figure 2





Figure 3



Architectural Detail

Lining Repair

STONHARD
1000 East Park Avenue

Maple Shade

New Jersey 08052

Scale:
NTS

Date:
06/23/2011

Drawing no.:
LNG.001

Drawn by:
KMB